




# Biweekly Blitz

December 31<sup>st</sup>, 2021



## Finneytown New K-6

Exterior - Roof detailing is ongoing. The windows and metal wall panels are being set and installed around the building.

Interior – The drywall walls are being finished and painted in the academic area while ceiling grid installation follows. Casework is being installed throughout the classrooms on both floors. Drywall is being hung in the administration wing. Above ceiling and in-wall MEP rough-in continues throughout the building.